

Minutes from Class April 21, 2004

- The Serial numbers on the boards are starting to rub off, please make sure that subsystems take care of replacing the serial numbers
- Please make sure that the Board Schematics Binder is updated to include information for all the versions of the boards
- Please start taking an inventory of the parts you will need for the remaining boards
- In case there is a need for cutting the consumption in power, subsystems will need to start removing the testing LEDs
- There is a need for instrumentation to measure current greater than 1 amp
- Reminder that the website for this class is ww2.lafayette.edu/~ece49204
- New Requirement: With no/limited intelligence concerning movement detection and location it is imperative that the robot is placed facing the mine at all times, specifically at the mission start of the shift the robot is presumed to be at the drop off shaft and facing the mine (facing down the shaft).